



# **SPECTRUM**

**Environmental Associates, Inc.**  
*'EXCEEDING OUR CLIENTS EXPECTATIONS OF EXCELLENCE'*

P. O. Box 1024  
Schenectady, NY 12301  
(518) 346-6374 (Phone)  
(518) 346-4062 (Fax)  
[www.4spectrum.com](http://www.4spectrum.com)

March 13, 2015

Mr. Rod Bromley  
B & B Recycling  
105 West Birmingham  
Broken Arrow, Oklahoma, 74011

RE: Beech-Nut Facility; Building 11

Dear Mr. Bromley:

Spectrum Environmental Associates, Inc. (Spectrum) has been retained by your firm to perform asbestos consulting services at the former Beech-Nut Facility located in Canajoharie, NY. The overall scope will be to identify and assess the condition of all the buildings remaining on the East side of the Canajoharie Creek which runs through the property. Based on information provided by you, Spectrum has reviewed previously prepared reports and has prepared this report as our demolition survey for Building #10 as identified on the site map provided.


Spectrum has reviewed the reports prepared by Churchill Environmental (dated 2/22/14) for the building interior and from Asbestos & Environmental Consulting Corp (dated 6/2/2014) for the building roof. TSI pipe insulation was identified throughout the warehouses which has been removed by others prior to our inspection of the building. The removal had resulted in an incidental disturbance which has been addressed under a site specific variance and was completed on March 9, 2014. With the interior clearance, it was safe to proceed with our inspection of the building to confirm all asbestos identified has been removed and to complete a demolition survey as requested.

On March 4, 2015, Spectrum visited the site and was able to perform an asbestos demolition survey in accordance with NYS ICR 56-5.1. The inspector of record was Adam Wyman (AH#07-07681) who is a certified EPA/NYS Asbestos Inspector. He performed a visual inspection in accordance with generally accepted industry standards and found no suspect materials that were not previously identified and determined to be negative for asbestos. Roof access was not available until March 13 at which time we were able to confirm that the roof on building 10 did not have a different flashing material. Therefore, the sampling performed by AECC showing the roof to be negative for asbestos has been confirmed.

In conclusion, Building #11 is clear of all asbestos containing materials and demolition may proceed as a non-asbestos project based on the findings of this report.

Should you have any questions concerning this report, please do not hesitate to contact our office at (518) 346-6374.

Respectfully Submitted,

A handwritten signature in black ink, appearing to read 'JAC II', with a long horizontal stroke extending to the right.

James A. Capasso II  
*Operations Manager*

Attachments:    Location Map of Building #11  
                      Licensing and Certifications